

1/4





FIG. 1



$$\begin{aligned} O \sin &= 0 \\ O \cos &= 0 \end{aligned}$$

FIG. 2

3/4




FIG. 3




FIG. 4

Wertepaare:

$U\sin(1), U\cos(1)$

$U\sin(2), U\cos(2)$

$U\sin(3), U\cos(3)$